











9775 S. Maryland Pkwy. Suite F. #168 Las Vegas NV 89123 O: 702 6162298 Fax: 702 616-9367

Inspection Standard

PO#: xxx Contact Person: xxx Vessel ETD: xxx Vessel ETA: xxx Quantity checked total: 200pcs	Product: Clear mirror Inspection Date: Inspector: PO quantities: 7000 PCS Vessel use:
---	---

A. Inspection Results: accepted or Rejected (add more lines if more items needed)

Customer Acceptable Fail Percentage: 5 %						
Item Name	Specification	Photo	Quantity Checked	Accepted	Rejected	Factory signature
4mm clear mirror 24" x 36" and 30" x 40" 1" Bevel	Dimension: 24" x 36" and 30" x 40"		how many of this item were checked for this specific specification	How many of the checked quantity were accepted?	How many were rejected?	Signature shows that factory is aware of acceptance of rejection
	4mm Thickness, Tolerance: ±0.25 mm					
	Tolerance of Length and Width: ±1.5mm					
	Tolerance of the Diagonal: ± 2mm maximum					
	Scratch: no visible scratches					
	Moldy Speckle: Should be invisible by eye					
	Fault Spot: no visible spots, seeds or other defects					
	Back Paint: thorough and consistent coverage – free from scratches, pin holes, patching or any other visible defects.					
	Mirror Quality: no visible distortion or staining					
	Width tolerance of the 1" Beve: +/- 1/32" on bevel width, consistent width all around, no visible distortion					

	Edge Quality: sharpness removed – no chips, cracks or other damage					
				Totals:		Factory Signature
				Accepted:	Rejected:	
1. Major defect description (add more lines if more notes needed)						
Item or Specification	Details and Photos					
			A small scratch in one piece.Rejected.			
	This part need pics		A small pin hole on the back of one piece. Rejected.			
2. Minor Defects descriptions (add more lines if more notes needed)						
Item or Specification	Details and Photos					
B. Packing:						
Item Name	Packing Specification	Photo	Quantity Checked	Accepted	Rejected	Factory signature
4mm clear mirror 24" x 36" 1" Bevel	185PCS/105.4*88*85/Crate,16 Crates G.W/N.W (TON): 33.76/32.80 Totalled CBM: 25.28 Totalled quantity:5920 PCS					
4mm clear mirror 30" x 40" 1" Bevel	135PCS/115.6*68*100.2/Crates,4 Crates G.W/N.W (TON): 8.44/8.20 Totalled CBM: 6.32 Totalled quantity:1080PCS					
1. Packing requirement description (add more lines if more notes needed)						
Item or Specification	Details and Photos					
1. Washed by pure water & drying	This part need pics					
2.Paper interleaved	This part need pics					
3. Wrapped by plastic film to keep all mirror sheet water free.	This part need pics					
4. Packed by sea worthy strong wooden crates with steel banding.	This part need pics					
2. Defects descriptions (add more lines if more notes needed)						
Item or Specification	Details and Photos					
C. Shipment Loading pictures. (Attach below)						
						
Inspector signature	Supervisor Signature	Factory manager signature	Customer Signature accept the goods as they have been inspected by my authorized representative.			

