











9775 S. Maryland Pkwy, Suite F, #168 Las Vegas NV 89123 O: 702 6162298 Fax: 702 616-9367
www.asianprosource.com

QC Report

PO#: xxx	Product: Clear mirror
Contact Person: xxx	Inspection Date: 21st,Nov,2006
Vessel ETA: 30th, November	Inspector: xxx
Vessel ETA: 25th, December	PO quantities:3500 PCS
Quantity checked total: 300 PCS	Vessel use: 20'

A. Inspection Results: accepted or Rejected (add more lines if more items needed)

Customer Acceptable Fail Percentage: 5 %						
Item Name	Specification	Photo	Quantity Checked	Accepted	Rejected	Factory signature
4mm clear mirror 24" x 36" and 30" x 40" 1" Bevel	Dimension:24" x 36" and 30" x 40"		how many of this item were checked for this specific specification	How many of the checked quantity were accepted?	How many were rejected?	Signature shows that factory is aware of acceptance of rejection
	4mm Thickness,Tolerance:±0.25 mm		300	300	0	
	Tolerance of Length and Width:±1.5mm		300	300	0	
	Tolerance of the Diagonal:± 2mm maximum		300	300	0	
	Scratch: no visible scratches		300	300	0	
	Moldy Speckle: Should be invisible by eye		300	300	0	
	Fault Spot: no visible spots, seeds or other defects		300	300	0	
	Back Paint: thorough and consistent coverage - free from scratches, pin holes, patching or any other visible defects.		300	299	1	Steven Sun
	Mirror Quality:no visible distortion or staining		300	300	0	
	Width tolerance of the 1" Beve: +/- 1/32" on bevel width, consistent width all around, no visible distortion		300	300	0	
Edge Quality: sharpness removed - no chips, cracks or other damage		300	298	2	Steven Sun	
				Totals 300		Factory Signature
				Accepted 297	Rejected 3	Steven SUN

1. Major defect description (add more lines if more notes needed)						
Item or Specification	Details and Photos					
	Very few pieces have a edge not well polished--it's reproduced already.					
2. Minor Defects descriptions (add more lines if more notes needed)						
Item or Specification	Details and Photos					
	Some very little patching in back print [0.4cm-0.6cm] is found on one piece of the mirror					
B. Packing:						
Item Name	Packing Specification	Photo	Quantity Checked	Accepted	Rejected	Factory signature
4mm clear mirror 24" x 36" 1" Bevel	185PCS/105.4*88*85/ Crate,16 Crates G.W/N.W (TON): 16.88/16.40 Totaled CBM: 12.64 Totaled quantity:2960 PCS		128			
4mm clear mirror 30" x 40" 1" Bevel	135PCS/115.6*68*100.2/ Crates,4 Crates G.W/N.W (TON): 4.22/4.10 Totaled CBM: 3.16 Totaled quantity:540 PCS		32			
1. Packing requirement description (add more lines if more notes needed)						
Item or Specification	Details and Photos					
1. Washed by pure water & drying	This part need pics				ACCEPT	
2.Paper interleaved	This part need pics				ACCEPT	
3. Wrapped by plastic film to keep all mirror sheet water free.	This part need pics				ACCEPT	
4. Packed by sea worthy strong wooden crates with steel banding.	This part need pics		THE LOADING PROCEDURE WILL BE INSPECTED			
C. Shipment Loading pictures. (Attach below)						
						
Inspector signature	Supervisor Signature	Factory manager signature	Customer Signature	I accept the goods as they have been inspected by my authorized representative.		
SONG WEI	Lily	Steven SUN	Remy Smith			

